


10. Set the LOAD/UNLOAD switch to LOAD (In Position).

Push in the LOAD/UNLOAD switch. The tape goes through a load process that takes between 5 and 7 seconds. Both lights come on steady as the tape reaches BOT (the beginning of usable tape).

The tape cartridge is now ready to use.



SHR-0305-84-C