


ITEM NO.	DESCRIPTION	FROM	TO	SIGNAL
1	14 BLK	1	PI-7	31GND
2	18 RED	2	PI-4	+5V
3	18 BRN	3	PI-14	-5V
4	18 BRN	4	PI-3	+20
5	18 ORN	5	PI-1	LO GND
6	18 BLK	6	PI-8	+5V
7	14 TWP	7	PI-1	DC LO
8	18 RED	8	PI-3	AC LO
9	18 VIO	9	PI-4	
10	11 YEL	10		



- NOTES:
1. USE THE WIRE (M) ITEM "10" AS SHOWN IN THE WIRE LIST. (SEE NOTE 3) AT EVERY BREAKOUT POINT.
 2. ATTACH MALE FASTON PINS (1000219-0) WITH 4 WOOD SCREWS (11 PLACES).
 3. USE CONN. BRKT. "C-MD-9305761-1" H18-O, MOUNT WITH 6 WOOD SCREWS. USE MATING CONN. "1209350-15."
 4. USE CONN. BRKT. "C-MD-9305761-1" H18-O, MOUNT WITH 6 WOOD SCREWS. USE MATING CONN. "1209350-06."
 5. DOT (•) INDICATES PANEL LOCATIONS FOR ASSEMBLY USE ONLY. COVER PANELS WITH MARKING TUBING TO PREVENT CUTTING HARNESS.

ITEM NO.	DESCRIPTION	QTY	UNIT	REF. DESIGNATION	SYN. QTY	REF. DESIGNATION	SYN. QTY
1	14 BLK	1	PI-7	31GND			
2	18 RED	2	PI-4	+5V			
3	18 BRN	3	PI-14	-5V			
4	18 BRN	4	PI-3	+20			
5	18 ORN	5	PI-1	LO GND			
6	18 BLK	6	PI-8	+5V			
7	14 TWP	7	PI-1	DC LO			
8	18 RED	8	PI-3	AC LO			
9	18 VIO	9	PI-4				
10	11 YEL	10					

ITEM NO.	DESCRIPTION	QTY	UNIT	REF. DESIGNATION	SYN. QTY	REF. DESIGNATION	SYN. QTY
1	14 BLK	1	PI-7	31GND			
2	18 RED	2	PI-4	+5V			
3	18 BRN	3	PI-14	-5V			
4	18 BRN	4	PI-3	+20			
5	18 ORN	5	PI-1	LO GND			
6	18 BLK	6	PI-8	+5V			
7	14 TWP	7	PI-1	DC LO			
8	18 RED	8	PI-3	AC LO			
9	18 VIO	9	PI-4				
10	11 YEL	10					