





ITEM NO.	DESCRIPTION	FROM	TO	TERMINAL	SIGNAL
1	ANG	3	P3-10	P1-1	45V
2	RED	4	P3-8	P1-2	45V
3	BLK	5	P3-4	P1-3	45V
4	GRY	6	P3-12	P1-4	45V
5	BLU	7	P3-11	P1-5	45V
6	BRN	8	P3-1	P1-6	45V
7	VIO	9	P3-3	P1-7	45V
8	YEL	10	P3-2	P1-8	45V
9	WHT	11	P3-15	P1-9	45V
10	WHT	12	P3-14	P1-10	45V
11	WHT	13	P3-16	P1-11	45V



USE TIE WRAPS (X) ITEM 4
APPROXIMATELY EVERY
TWO (2) INCHES WHEN
NECESSARY AND AT EVERY
BREAKOUT POINT.
2. DO NOT INDICATE MAIL LOCATIONS FOR ASSEMBLY
FLY USE ONLY. COVER HALLS WITH SHRINK
TUBING TO PREVENT CUTTING HARNESS.
3. USE CONN BRKT GND-93C376-H6-0
MOUNT WITH WOOD SCREWS. USE
MATING CONN 1009350-3.
4. USE CONN BRKT GND-93C376-H6-0
MOUNT WITH WOOD SCREWS. USE
MATING CONN 1009350-3.
5. USE CONN BRKT GND-93C376-H6-0
WITH PLATE B-MD-9305767-2-24 USE
TAPE DEC 7008734 & CONN BRKT DEC 7009123
(2009123) REMOVE PINS FLANGES AS
SHOWN IN DETAIL "A". MOUNT WITH
WOOD SCREWS.

REV	DESCRIPTION	DATE	BY	CHK
1	INITIAL DESIGN	10/1/72	W. J. HARRIS	W. J. HARRIS
2	REVISION	10/1/72	W. J. HARRIS	W. J. HARRIS
3	REVISION	10/1/72	W. J. HARRIS	W. J. HARRIS
4	REVISION	10/1/72	W. J. HARRIS	W. J. HARRIS
5	REVISION	10/1/72	W. J. HARRIS	W. J. HARRIS
6	REVISION	10/1/72	W. J. HARRIS	W. J. HARRIS
7	REVISION	10/1/72	W. J. HARRIS	W. J. HARRIS
8	REVISION	10/1/72	W. J. HARRIS	W. J. HARRIS
9	REVISION	10/1/72	W. J. HARRIS	W. J. HARRIS
10	REVISION	10/1/72	W. J. HARRIS	W. J. HARRIS
11	REVISION	10/1/72	W. J. HARRIS	W. J. HARRIS
12	REVISION	10/1/72	W. J. HARRIS	W. J. HARRIS
13	REVISION	10/1/72	W. J. HARRIS	W. J. HARRIS
14	REVISION	10/1/72	W. J. HARRIS	W. J. HARRIS
15	REVISION	10/1/72	W. J. HARRIS	W. J. HARRIS
16	REVISION	10/1/72	W. J. HARRIS	W. J. HARRIS
17	REVISION	10/1/72	W. J. HARRIS	W. J. HARRIS
18	REVISION	10/1/72	W. J. HARRIS	W. J. HARRIS
19	REVISION	10/1/72	W. J. HARRIS	W. J. HARRIS
20	REVISION	10/1/72	W. J. HARRIS	W. J. HARRIS